



Output Signals options



TS - Sensor Standard
outputs: analog 0 - 1 V



TS - Sensor Code A2
outputs: analog 0 - 10 V




Output Signals options



TS1-Sensor Code A3

outputs: 4-20 mA




Output Signals options



TS1-A10 Sensor without integrated amplifier


outputs: mV / V



Output Signals options



TS1-232 Sensor to PC outputs: RS 232 and analog



Output Signals options



TS1-232-H Sensor to PC outputs: RS 232 and analog

